

**AHERA REINSPECTION  
The Gold Beach High School School  
at  
29516 Ellensburg  
Gold Beach, Oregon 97444**

**Prepared For:**


**Tim Wilson, Superintendent  
Central Curry School District SD 1  
29516 Ellensburg Avenue  
Gold Beach, Oregon 97444**

**EIS Job No. 2021030.Gold Beach High School**

**Prepared By:**

**Charles A. Spear  
AHERA Certification #IRO-21-2439A**

**Environmental Inspection Services  
11981 Fargo Road  
Aurora, Oregon 97002  
cell # (503) 680-6398  
E MAIL: charles\_a\_spear@yahoo.com**





**Charles A. Spear, Partner**

**May 15, 2021**



**EIS**  
**ENVIRONMENTAL INSPECTION SERVICES**

 Bus: 503.678.5063 | Cell: 503.680.6398

 11981 Fargo Road, NE, Aurora, OR 97002

 [www.environmentalinspectionsservices.net](http://www.environmentalinspectionsservices.net)



## **TABLE OF CONTENTS**

<b><u>DESCRIPTION</u></b>	<b><u>PAGE NO</u></b>
<b>EXECUTIVE SUMMARY.....</b>	<b>1-4</b>
<b>ACCREDITATION / RESUME.....</b>	<b>5-8</b>
<b>REGULATIONS (BACKGROUND).....</b>	<b>9-11</b>
<b>ACTIVITY (BACKGROUND).....</b>	<b>12</b>
<b>REINSPECTION REPORT.....</b>	<b>13</b>
<b>REINSPECTION SCOPE OF WORK.....</b>	<b>13</b>
<b>SUMMARY OF FRIABLE / NONFRIABLE ACBM .....</b>	<b>14-15</b>
<b>RECOMMENDATIONS AND CONCLUSIONS.....</b>	<b>16</b>
<b>LIMITATIONS.....</b>	<b>17</b>

### **APPENDIX 1.0**

#### **SITE PLAN**

### **APPENDIX 2.0**

#### **RECORDING FORMS FOR ASSESSMENT DATA**

### **APPENDIX 3.0**

#### **REGULATIONS**

May 15, 2021

EIS JOB No. 2021030.Gold Beach High School

Tim Wilson, Superintendent  
Central Curry School District  
29516 Ellensburg Avenue  
Gold Beach, Oregon 97444

RE: Asbestos 2021 AHERA 3-year Reinspection of the Gold Beach  
High School located at 29516 Ellensburg in Gold Beach,  
Oregon

Dear Mr. Tim Wilson,

The Federal Asbestos Hazard Emergency Response Act (commonly referred to as AHERA) was signed into law in 1986. AHERA requires both private and public non-profit primary and secondary schools to inspect all buildings that are leased, owned, or otherwise used as school buildings for the presence of asbestos-containing building materials (ACBM). The U.S. Environmental Protection Agency (EPA) published regulations and enforces AHERA.

EIS is pleased to present the May, 2021 AHERA reinspection for The Gold Beach High School located at 29516 Ellensburg in Gold Beach, Oregon. The subject school has been substantially managed and maintained. Suspect asbestos-containing building materials (ACBM) includes ceiling tile mastics; nine-inch vinyl floor tiles; moulding mastic adhesives; original ceiling tiles; thermal system insulation in the boiler room, ebonite table tops. No problematic conditions were observed. No special asbestos-containing materials (ACM) conditions were noted at that time of the AHERA inspection.

Many varieties of intact vinyl floor tiles and floor linoleum were observed in the building. No concerns were noted. Fire doors and hard fittings originally noted in the boiler room were in good condition. No damages were noted in the building material. Exposed moulding mastic as noted in data sheet No. 2 should be repaired and covered as typical.



The subject original functional spaces were examined throughout for the presence of confirmed and suspect asbestos-containing building materials (ACBM). All representative functional spaces and relative homogeneous sampling areas were examined during the inspection process.

A total of twenty-seven (27) data sheets were completed for the school and no noteworthy damages were observed. The sheets summarize the accessibility and condition of identified confirmed and/or suspect asbestos-containing building materials (ACBM) observed throughout the original Gold Beach High School building.

All identified ACBM are candidate materials for in-place operations and maintenance and asbestos abatement is not recommended or required. The condition of the existing suspect ACBM is good to excellent and considered to be protective of student safety and health. No bulk samples were collected from suspect asbestos-containing building materials (ACBM).

#### **THERMAL SYSTEM INSULATION (TSI)**

No asbestos-containing thermal system insulation (TSI) piperun materials were observed in overhead piperuns in the study areas. TSI seals, and gaskets were observed within a totally remodeled boiler room on-site. Intact seals, gaskets, and pipe lagging were noted in the boiler room areas.

#### **RESILIENT FLOOR COVERINGS** **(VINYL FLOOR TILE & SHEET FLOOR LINOLEUM)**

Several varieties of intact, maintained and suspect resilient floor coverings were observed in the subject building to include 1' white tile, tan pattern linoleum, 9" gray VAT, 9" tan VAT, 1' tan VAT, 9" grey-red VAT, 1' black tile and 9" Salmon VAT. No VAT damages were observed. No samples were collected from vinyl floor tile.

All examined floor coverings are in good to excellent condition, well maintained, accessible, and intact. No significant floor covering condition or damage concerns were noted. Minor damaged floor tiles may be replaced as a repair item. Refer to sheet No.s 3,5,6,11,12,13,15,20 for references.



### **COVE-BASE ADHESIVE**

Cove-base mastic adhesive was observed on floor moulding within various functional spaces throughout the subject elementary school. The moulding is intact and in good condition. No samples were collected in moulding mastics. Refer to sheet No.s 20,21,23,26,27 for details.

### **TAPE JOINT COMPOUND**

This compound is typically applied to taped joints applied between sheet rock wall surfaces. Tape joint compound exists on sheet rock panels throughout the subject building. The compound usage was extensive and is likely throughout the entire structure original pre-1980 wall panel tape joints. The compound is in good condition, sealed and or encapsulated, and a candidate building material for operations and maintenance.

### **ACOUSTIC CEILING TILES**

Large perforation ceiling tiles were observed on ceiling surfaces in the hallways. No samples were collected from ceiling tiles or mastics. No specific ceiling tile quality concerns were noted. No problematic ceiling tiles were observed on ceiling surfaces throughout the building. Refer to sheet No.s 1,4,7, 14, and 22 for details.

### **PLASTER (SKIM COAT)**

Original wall surfaces have plaster skim coat applications observed within functional areas of the building. No samples were collected. EIS noted no plaster concerns. Plaster surfaces were observed throughout the structure.

The wall plaster surfaces were noted to be in good condition and candidate building materials for in-place operations and maintenance. The existing plaster surfaces are sealed and coated in latex paint applications and considered to be in good condition. No concerns were noted. Refer to sheet No. 24 for details.

All suspect and previously analytically confirmed ACBM were noted to be in good to excellent condition. All ACBM are considered candidate building materials for operations and maintenance in accordance with the standard O&M recommendations stated in The AHERA Management Plan and the EPA Manual known as Managing Asbestos in Place - A Builder Owners Guide to Operations and Maintenance Programs for Asbestos-Containing Materials per EPA Manual No. 20T 2003 dated July, 1990.

Candidate ACBM include skim coat applications on wall surfaces, acoustic ceiling tiles, ceiling tile mastics, moulding mastic adhesive, vinyl floor linoleum, TSI, and vinyl asbestos tiles. No asbestos containing debris or other related asbestos material concerns were noted at the aforementioned building.

No asbestos containing debris, damaged and disturbed ACBM or other related asbestos material concerns were noted at the aforementioned materials. No asbestos-containing thermally insulated pipe runs were noted. Asbestos abatement is not recommended or necessary at this time.

Thank you for the opportunity to perform the May, 2021 asbestos reinspection. Progress has been made since the AHERA Management Plan issuance and initial inspections. The Gold Beach High School has been well maintained and no asbestos material safety concerns were noted. Exposed mastics as noted in sheet No. 2 should be covered. If there are any questions feel free to contact us at (503) 680-6398.

Respectfully,

  
Charles A. Spear

Partner

AHERA Inspector No. IRO-21-2439A

This reinspection of the Gold Beach High School Building and outbuildings was performed on Monday, April 26, 2021 by Charles A. Spear. AHERA Inspector Certification No. IRO-21-2439A. The AHERA Inspector expiration date is March, 2022. All inspection / assessment activities were performed in accordance with the reinspection requirements of Part III 40 CFR Part 763. Asbestos-Containing Materials in Schools; Final Rule and Notice.



## **RESUME**

**CHARLES ARTHUR SPEAR  
REGISTERED ENVIRONMENTAL ASSESSOR  
REA - 01241**

**AHERA INSPECTOR (EPA CERTIFICATION NO. IRO-21-2439A)**

**CERTIFIED ENVIRONMENTAL INSPECTOR  
CEI - 10364**

### **Professional Background**

Charles A. Spear, President and founder of Environmental Inspection Services has over 20 years technical experience ranging from facility food technologist to hazardous waste site remediation at Federal SUPERFUND sites from California to Maryland. Mr. Spear has successfully performed over 2,000 Phase One, Phase Two, and Phase Three Environmental Site Assessment inspections on properties from California to Alaska and east to Maryland. Mr. Spear has managed such projects as spilled mustard gas and organophosphate remediation as a sergeant of the U.S. Army Chemical Corps Technical Escort Unit Drill & Transfer Unit at Umatilla Army Depot and removal of leaking solvent underground storage tanks in California and Oregon.

Specifically, Mr. Spear has worked with clients such as: the International Fabric Care Industry (IFI), the U.S. Environmental Protection Agency, The U.S. Department of Defense, The Oregon Department of Environmental Quality (ODEQ), The Oregon Department of Forestry, INTEL, Sun Microsystems, IBM, Rohm & Haas, General Electric, AT&T, Texaco, Unocal, BP, Lockheed Missile and Space Center, FMC Corporation, Oregon Department of Fish & Wildlife, Washington Department of Fish & Wildlife, City of Beaverton, City of Hillsboro, City of Corvallis, Housing Authority of Portland, Northwest Oregon Housing Authority, Washington County Department of Housing, Housing & Urban Development, numerous lenders and mortgage companies, many private development and site remedial site projects, and many attorneys and investors.

Mr. Spear managed complex tank farm removals at Xidex Corporation in Sunnyvale, California and was the site cleanup manager at the Rose City Plating Site currently developed as the Oregon Convention Center. Mr. Spear is a certified hazardous waste professional who has coupled military experience as a Nuclear, Biological and Chemical Specialist (U.S. Army MOS 54E20) with experience as a professional research engineer in both the corrugated paper and petroleum industries.



Mr. Spear has managed food industry quality control as an inplant food technologist and prepared cost reduction programs as a corrugated box board industrial engineer in Dallas, Texas. He is currently registered with the states of California, Washington, and Oregon and is an active member of the national respected Environmental Assessment Association. Due diligence projects have been performed throughout the United States from Fairbanks, Alaska to San Diego, California.

Professional experience includes the following:

### **Professional Experience**

- \* Dry Cleaner Inspections
- \* Environmental Consultation
- \* Waste Reduction Audits
- \* Regulatory Compliance Audits
- \* Drum Yard Clearances
- \* Tank Farm Removals/Replacements
- \* Lab Packaging & Supervision
- \* Environmental Site Assessments
- \* Superfund Site Remediation
- \* Hazardous Waste site Project Design & Management
- \* Habitat/Wetlands Restoration
- \* AHERA asbestos inspections for school districts
- \* Landfill Remediation
- \* Agricultural assessments
- \* Indoor air quality inspections

### **Professional Employment/Consultation**

- \* C.F.S. Continental Coffee, Inc., Food technologist, Chicago, Illinois
- \* Holiday Industries, Research Engineer, Grand Prairie, Texas
- \* Alton Packaging Corporation, Industrial Engineer, Dallas, Texas
- \* U.S. Army Chemical Corps., Nuclear, Biological, Chemical Specialist - Special assignment - Umatilla Army Depot (DATS)
- \* U.S. Army Chemical Corps. Technical Escort Unit in Edgewood, Maryland
- \* Rollins Environmental Services, Remedial Project Manager
- \* Crown Environmental Services, Technical Director, Redmond, California
- \* Dames & Moore, Design Engineer, Portland, Oregon
- \* Pegasus Environmental Management Services, Director of Technical Services
- \* Pacific Tank & Construction, Manager of Estimation, Portland, Oregon
- \* Enviro-Logic Inc., Director of Environmental Site Assessment Division
- \* Environmental Inspection Services Inc., Founder/President

### **Professional Education**

- \* Bachelor of Science, Chemistry, Northeastern Illinois University, 1978
- \* U.S. Army Chemical School, Ft. McClellan, Alabama, 1983
- \* U.S. Army Technical Escort Unit, Accident/Incident Response Training Center 1983
- \* Registered Environmental Assessor REA - 01241
- \* Certified Environmental Inspector CEI - 10364
- \* AHERA Certified Asbestos Inspector 342-48-8305
- \* ODEQ Soil Matrix Assessor & UST Decommission Supervisor
- \* Washington DOE Registered Environmental Assessor
- \* Wetland Specialist - Training Wetlands Institute 1997
- \* EPA/HUD Lead-Based Paint (LBP) Inspector & Risk Assessor
- \* ASTM Certification Training, May, 2004

### **Additional Education**

- \* Joint Military Material Packaging & Transportation
- \* Asbestos Abatement Seminar attendance 1987
- \* Thin Layer Chromatography, 1989
- \* Oregon Registered Underground storage Tank Supervisor, 1998
- \* Oregon Registered Soil Matrix Assessor, 1998
- \* Washington Registered Assessor, 1991
- \* Washington Registered Underground Storage Tank Supervisor, 1991
- \* Wetland Training Institute Delineation Course Study University of Portland March 1997
- \* 40-Hour HAZMAT Certified
- \* AHERA-Certified Inspector

### **Special Skills**

- \* Facility Environmental Compliance Audits
- \* ASTM standard Environmental Site Assessments
- \* Computer Programming
- \* Organic surfactant chemical synthesis and analysis
- \* Hazardous Waste Site remediation/ estimating/ standards development
- \* Design of filtration systems, batch and continuous process optimization studies
- \* QA/QC Procedures
- \* SUPERFUND Site Management
- \* Industrial/ Research Engineering
- \* Hazardous Waste Site Remediation/ Consultation
- \* Wetlands Delineation and Habitat Restoration

## **Certification**

- \* U.S. Army MOS 54E20 - U.S. Army Chemical Corps.
- \* International Fire Code Institute (IFCI) Certified UST Supervisor
- \* International Fire Code Institute (IFCI) Certified Soil Matrix Assessor
- \* Certified Hazardous Waste Manager
- \* 40-hour OSHA Training
- \* 40-hour OSHA Supervisor Training
- \* Registered Environmental Assessor (DOE)
- \* DEQ Registered UST Supervisor, April 2021
- \* DEQ Registered Soil Matrix Assessor
- \* Resolution Trust Corporation (RTC) approved Environmental Assessor
- \* California Registered Environmental Assessor (REA-01241)
- \* Department of Ecology (DOE) Registered Environmental Assessor
- \* Environmental Assessment Association, Certified Environmental Inspector & Transaction Specialist (CEI-10364)
- \* AHERA Certified Asbestos Inspector AHERA # IRO-21-2439A
- \* Wetland Delineator Graduate Wetland Training Institute, University of Portland 1997
- \* EPA/HUD LBP Inspector & Risk Assessor
- \* ASTM certification



## **REGULATIONS**

### **Asbestos - Background**

Asbestos is generally referred to as six naturally occurring fibrous minerals found in certain types of rock formations. The minerals Chrysotile, Amosite, and Crocidolite have been most commonly utilized in building materials. Asbestos is typically separated into very thin fibers. Asbestos is strong, incombustible, and corrosion resistant and was utilized early in the century into the 1970's. Asbestos may cause substantial health problems when it is inhaled in sufficient quantities.

Asbestos is considered to be a hazardous air contaminant and a known human carcinogen. Once used extensively as an insulation material, asbestos has been banned from most construction and manufacturing since the mid-1970's. The most dangerous forms of asbestos are those materials containing asbestos which can be easily crushed or crumbled known as "friable asbestos". Friable asbestos is dangerous since asbestos fibers can be easily released into the air. Such activities as remodeling and demolition projects are likely to disturb asbestos. If asbestos-containing building materials (ACBM) are not handled properly then these types of projects can pose as a serious threat to workers and the general public.

### **Regulatory Background**

In 1986, Congress enacted the Asbestos Hazard Emergency Response Act (AHERA or TSCA Title II) which mandated a regulatory program to address asbestos hazards in schools. A copy of the Environmental Protection Agency Asbestos Model Accreditation Plan interim Final Rule (59FR2236-5260) is enclosed for reference. President Reagan signed into law the Asbestos Hazard Emergency Response Act (AHERA) on October 22, 1986. This law enacted, among other provisions, Title 2 of the Toxic Substances control Act (TSCA) 15 U.S.C. Section 2641 through 2654; Section 203 of Title II, 15 U.S.C. 2643. Generalized regulations are attached for review.

**AHERA requires the following:**

- (1.0) - Perform an original inspection and periodic re-inspections every three years for asbestos containing material;
- (2.0) - Develop, maintain, and update an asbestos management plan. A copy must be kept in the school building, as well as in the districts administrative office;
- (3.0) - Provide an annual written notification to parent, teacher, and employee organizations regarding the availability of the school's asbestos management plan for review and any asbestos abatement actions taken or planned in the school;
- (4.0) - Designate a contact person (also known as the asbestos designee) to ensure the responsibilities of the local education agency are properly implemented. Details on the asbestos designee's responsibilities may be found at : [www.epa.gov/region02/ahera/ampauditchecklist.pdf](http://www.epa.gov/region02/ahera/ampauditchecklist.pdf)
- (5.0) - Perform a periodic visual surveillance every six months of all known or suspected asbestos-containing building material;
- (6.0) - Provide custodial staff with asbestos hazard awareness training

Note: If a building has never been inspected for asbestos, a new AHERA inspection must be completed as soon as possible. Pursuant to AHERA Section 763.85(a0, any building leased or acquired on or after October 12, 1988, that is used as a school building shall be inspected for asbestos prior to use as a school building. In the event that the emergency use of an uninspected building as a school building is necessitated, such building must be inspected for asbestos within 30 days after the commencement of such use.

Section 112 of the Clean Air Act (CAA) requires EPA to develop emission standards for hazardous air pollutants. In response to this section the EPA published a list of hazardous air pollutants and promulgated the National Emission Standards for Hazardous Air Pollutants (NESHAP) regulations.

The asbestos NESHAP (40 CFR 61, Subpart M) addresses milling, manufacturing and fabricating operations, demolition, and renovation activities, waste disposal issues, active and inactive waste disposal sites and asbestos conversion processes.

In the initial Asbestos NESHAP rule promulgated in 1973, a distinction was made between building materials that would readily release asbestos fibers when damaged or disturbed and those materials that were unlikely to result in significant fiber release. The terms "friable and non-friable" were used to make this distinction. EPA has since determined that, if severely damaged, or otherwise non-friable materials can release significant amounts of asbestos fibers.

Friable asbestos-containing material (ACM) is defined by the Asbestos NESHAP as any material containing more than one percent (1%) asbestos as determined using the method specified in Appendix A, Subpart F, 40 CFR Part 763, Section 1, Polarized Light Microscopy (PLM), that when dry, can be crumbled, pulverized, or reduced to powder by hand pressure (section 61.141). Non-friable material is ACM not reduced to powder by similar circumstances.



## **ACTIVITY**

### **Background**

It is the responsibility and primary mission of the AHERA inspector to determine whether ACBM is present in a building and to assess the physical characteristics of the ACBM in the structure. The inspection process includes an investigation of available records; an inspection of the functional spaces; an assessment of the condition of observed ACBM; reviews of available architectural and as built plans; review of work change orders; examination of material specifications indicating the presence of ACBM; examination of friable and non-friable ACBM; delineation of homogenous sample areas; collection of samples; and information on ACBM conditions.

The Gold Beach High School gymnasium, boiler room, cafeteria, classrooms, galleries, vestibules, and hallways were examined for suspect ACBM during the AHERA reinspection. Data forms were completed. The completed forms were edited for completeness and potential problem areas or areas requiring abatement or extensive repair were noted. Copies of the forms are attached for review and reference and generally represent a condition evaluation and summary of the potential homogeneous sampling areas and functional space areas. No concerns were noted regarding all examined ACBM.

## **REINSPECTION**

Charles A. Spear conducted a triennial asbestos reinspection of the Gold Beach High School building on Monday, April 26, 2021. Activities included blueprint and/or facility floor plan review; an interview with the maintenance supervisor; and a physical reinspection examination of all suspect and confirmed friable and non-friable asbestos-containing building materials at the subject Gold Beach High School. The school and class rooms are well maintained.

The accredited EIS inspector performed a preliminary examination of the subject structure. The AHERA inspector confirmed the existence of suspect asbestos-containing building materials (ACBM) such as vinyl asbestos floor tiles; moulding mastic adhesives; skim coat plaster applications on sheet rock; thermal system insulation on seals gaskets, and boiler pipe lagging and acoustic ceiling tiles ceiling tile adhesives, and miscellaneous and cementitious materials.

All accessible areas to include The Gold Beach High School gymnasium, cafeteria, weight rooms, original kitchen, shops, science room, galleries, vestibules, and storage rooms and hallways were examined for suspect ACBM during the AHERA reinspection. All the aforementioned functional areas were visibly inspected during this AHERA reinspection. No significantly damaged ACBM was observed during there inspections.

The building walkover revealed all asbestos-containing materials to be candidate building materials for Operations and Maintenance. The original AHERA Management Plan confirmed asbestos in several forms. Operations and Maintenance is recommended for all confirmed and suspected asbestos-containing materials to include vinyl asbestos tiles (VAT); and miscellaneous materials. No ACBM concerns were noted for the aforementioned materials. Asbestos abatement is not recommended for the subject facility ACBM at this time. Minor repair of damaged areas is adequate and protective.

All the aforementioned materials are in good condition and candidate materials for Operations and Maintenance. No noteworthy damages or disturbances of ACBM were observed. These materials have low potential for damage with no influence of vibration or potential for air erosion.

## **SUMMARY OF FRIABLE / NONFRIABLE ACBM**

Staff and maintenance personnel are encouraged to consult the forms prior to maintenance activities planned for suspect ACBM.

### **1.0 Vinyl Asbestos Tile (VAT) Non-Friable**

The school boiler room is modern and no concerns were noted. VAT was observed on classroom floors and hallways.

Description - a nonfriable vinyl material with vinyl filler and binder. An adhesive mastic is utilized to adhere to the vinyl floor surfacing to another substrate. The VAT asbestos content is described as a separate matrix from the adhesive mastic. VAT subject to removal must be removed in whole pieces by using the proper tools with wetting and proper handling, wrapping and disposal procedures. No poor condition floor coverings were noted.

### **AHERA Classification-Miscellaneous**

Products not utilized as TSI or surfacing materials are classified as miscellaneous materials. Materials such as transite pipe, ceiling tiles, fire doors, gaskets, vinyl floor coverings, duct work flexible connections, roofing felt, roofing flashing, and fume hood ducting and paneling are miscellaneous materials. These miscellaneous materials were noted in various areas of the subject building as noted in data sheets. Samples were not collected from suspect ACBM.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds. No popcorn ceiling materials were observed on-site.



## **2.0 Thermal System Insulation (TSI)**

AHERA Classification - TSI

Insulation used on mechanical systems to prevent heat ,loss or gain and condensation. Steam and hot water lines, boiler tanks, expansion joints, fittings and other mechanical systems are commonly insulated with pre-fabricated asbestos-containing magnesium silicate. The material is typically white in color and is encased in a plaster-impregnated canvas wrapping. Asbestos containing mud compounds are often used on elbows, valves, identification plates, miscellaneous fittings, and for other special applications on mechanical systems. Some Pipe run TSI has been abated. Presumed asbestos containing pipe lagging was observed in the basement area. Refer to sheet No.s 15 for details.

## **3.0 Acoustic ceiling Tiles, Suspect - Non Friable Miscellaneous**

Fibrous acoustical ceiling tiles, varying in size from one foot square to two by four foot lengths. Fibrous material integrated with cellulose binder and directly adhered to ceiling surfaces. The material in most classrooms is in good condition. Ceiling tiles are easily damaged and may create a dust hazard if the material is broken, abraded, cut, or drilled. Acoustical ceiling tiles were observed on ceiling surfaces in the classrooms. The adhesive tabs to the tiles are suspect ACM and are candidate building materials for in-place operations and maintenance. No ceiling tile or mastic concerns were noted. Refer to Sheet No.s 14,7,10,14,22 for details.

## **4.0 Adhesive mastic**

Typical to adhere ceiling acoustic panels to underlying substrate. Material is non-problematic and non-friable.

ACM sprayed or troweled onto surfaces for acoustical, decorative, or fireproofing purposes. Asbestos is blended in to spray-applied and troweled-on products to include structural fireproofing, stucco, plaster, acoustical and decorative surfaces, and joint compounds. Refer to sheet No.s 20,21,23,26, and 27 for details.

## **(5.0) - Sprayed-on acoustic popcorn ceiling materials**

No suspect popcorn ceiling materials were observed within the subject building. Popcorn ceiling materials are an acoustic sprayed-on application spray applied to ceiling sheet rock surfaces as an acoustic material.

## **RECOMMENDATIONS AND CONCLUSIONS**

All vinyl asbestos tiles flooring materials, acoustic ceiling tiles, ceiling tile mastics, and miscellaneous skim coat plaster applications on sheet rock wall panels materials are candidate building materials for Operations and Maintenance. Asbestos abatement of confirmed asbestos-containing building materials is not recommended at this time.

In all areas where work or work-related activities are planned materials must be properly tested and classified as non-asbestos. If confirmed, all asbestos containing building materials must be handled, managed, or removed in accordance with state and federal regulations. Asbestos abatement is not recommended or required at this time. No environmental concerns regarding ACM at the Gold Beach High School Elementary School were noted at this time.

All confirmed ACM scheduled for material damage or disturbance by renovation, remodeling, or demolition must be properly abated in accordance with EPA and ODEQ recommendations and procedures.

All maintenance workers and related staff must handle ACM in accordance with the protective provisions of the Oregon Occupational Safety and Health Administration (OSHA) requirements. Maintenance and staff personnel are encouraged to follow the management recommendations of the AHERA management plan and related operations and maintenance procedures as outlined in the appendix of this letter.



## **LIMITATIONS**

This report was prepared in accordance with generally accepted AHERA standards of environmental reinspection practice at the time this investigation was performed. Evaluations of the conditions at the site for the purpose of this investigation are made from a limited number of observation points and may be subjective in some cases. The subject school district is solely responsible for providing any notices or disclosures to concerned public agencies or to the public.

Environmental Inspection Services has prepared this report based on information collected from available records and files. The scope of this investigation is limited and did not include subsurface exploration or chemical screening of soil and groundwater beneath the site. No bulk material samples were collected from the subject school suspect ACBM for the purposes of this reinspection.

The findings and conclusions are not to be regarded as scientific certainties. Findings are based on professional judgement concerning data significance. Evaluation of the presence of asbestos-containing building materials in the subject school is based upon actual analytical test results, EIS gathered data initially furnished in previous reinspection and the site specific AHERA Management Plans prepared by others. This report is an expression of professional opinion and is not a warranty express or implied.

## **APPENDIX 1.0**


### **SITE PLAN**

# Gold Beach High School DESIGNATED AREAS FOR FIRE DRILL

29516 Ellensburg Avenue  
Gold Beach, OR 97444

TIM WILSON

## SCHOOL MAP



These rooms should remain on front lawn.  
Do not go into parking lot.

PLAN I: Regular procedure (this page)  
PLAN II: Catastrophe: ALL STUDENTS REPORT  
TO FRONT LAWN FOR DIRECTIONS



## **APPENDIX 2.0**

### **RECORDING FORMS FOR ASSESSMENT DATA**

## RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING High School FLOOR MAIN  
FUNCTIONAL AREA Cafe HOMOGENEOUS MATERIAL 9" ac ceiling tiles / mca  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING CEILING ☒ WALLS OTHER  
DESCRIPTION OF MATERIAL 9" ceiling tiles / mca

APPROXIMATE AMOUNT OF MATERIAL (SF) 5125 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

## DESCRIPTION

9" ceiling tiles  
APPROXIMATE AMOUNT OF MATERIAL (SF) 5125 (LF) \_\_\_\_\_  
FRIABLE: (YES) X (NO) \_\_\_\_\_  
NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: 110 feet

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>
DESCRIPTION	<u>0.64</u>	

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
COMMENTS 0.64

INSPECTOR: Charles Spear ACCREDITATION NO. 720-21-24374  
SIGNATURE: Charles Spear DATE: 4/26/21

## RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAN  
FUNCTIONAL AREA hallways HOMOGENEOUS MATERIAL exposed material  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING CEILING WALLS OTHER X  
DESCRIPTION OF MATERIAL exposed material

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 200

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC X FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

## DESCRIPTION

exposed material  
APPROXIMATE AMOUNT OF MATERIAL (SF) 20 (LF) \_\_\_\_\_  
FRIABLE: \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: exposed material requires repair

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE X LOW \_\_\_\_\_  
DESCRIPTION \_\_\_\_\_

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
COMMENTS \_\_\_\_\_

INSPECTOR: Charles Spear ACCREDITATION NO. ILD-21-2439A  
SIGNATURE: Charles Spear DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAIN  
 FUNCTIONAL AREA wood shop (Juss) HOMOGENEOUS MATERIAL 1' grey tile  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING f CEILING WALLS OTHER  
 DESCRIPTION OF MATERIAL 1' grey tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 160 (LF) 160

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC FLOOR CEILING

DESCRIPTION

1' grey tile  
 APPROXIMATE AMOUNT OF MATERIAL (SF) 160 (LF) 160  
 FRIABLE: (YES) X (NO)     
 NON-FRIABLE (YES)    (NO) X  
 WARNING LABELS (YES)    (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES)    (NO)   

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION    PHYSICAL X WATER    FIRE     
 EXTENT OF DAMAGE: LOCALIZED    DISTRIBUTED X  
 PERCENT OF DAMAGE: 0%    1-10% X 10-25%    25-100%     
 OVERALL RATING: GOOD X FAIR    POOR     
 DESCRIPTION: inlet

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE <u>  </u>
POTENTIAL FOR CONTACT:	HIGH <u>  </u>	MODERATE <u>  </u> LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH <u>  </u>	MODERATE <u>  </u> LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH <u>  </u>	MODERATE <u>  </u> LOW <u>  </u>
OVERALL RATING:	HIGH <u>  </u>	MODERATE <u>  </u> LOW <u>  </u>
DESCRIPTION	<u>O&amp;M</u>	

LOCATION IN AIR PLENUM: YES X NO     
 COMMENTS O&M

INSPECTOR: Charles Spear ACCREDITATION NO. IDO-21-2439A  
 SIGNATURE: Charles Spear DATE: 4/26/21 -v

# RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAIN  
FUNCTIONAL AREA old gym HOMOGENEOUS MATERIAL 9" ceiling fiber  
TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 10/15 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

## DESCRIPTION

9" ceiling fiber  
APPROXIMATE AMOUNT OF MATERIAL (SF) 10/15 (LF) \_\_\_\_\_  
FRIABLE: (YES) X (NO) \_\_\_\_\_  
NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: old gym

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>
DESCRIPTION	<u>old gym</u>	

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
COMMENTS old gym

INSPECTOR: Charles Spear ACCREDITATION NO. EDD-21-24394  
SIGNATURE: Charles Spear DATE: 4/26/21 - mu



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING 415 FLOOR MAIN  
 FUNCTIONAL AREA Landings HOMOGENEOUS MATERIAL 9" few part cut  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" few part cut

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION 9" few part cut

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF) \_\_\_\_\_  
 FRIABLE: (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: intact

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
 POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW \_\_\_\_\_  
 DESCRIPTION OK

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
 COMMENTS OK

INSPECTOR: Charles Spear ACCREDITATION NO. IPD-21-24394  
 SIGNATURE: Charles Spear DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAIN  
 FUNCTIONAL AREA Class 5 HOMOGENEOUS MATERIAL 9" fan VAG  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" VAG

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 K per (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION 9" fan VAG

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 K per (LF) \_\_\_\_\_  
 FRIABLE: \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED \_\_\_\_\_  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: Open

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE \_\_\_\_\_  
 POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW X  
 DESCRIPTION Open

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
 COMMENTS Open

INSPECTOR: Charles Spear ACCREDITATION NO. FD-21-24357  
 SIGNATURE: Charles Spear DATE: 4/26/21 -mw

## RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR 1st  
 FUNCTIONAL AREA transition HOMOGENEOUS MATERIAL 9" acc ceiling tiles  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 1162 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

## DESCRIPTION

9" ceiling tiles  
 APPROXIMATE AMOUNT OF MATERIAL (SF) 1162 (LF) \_\_\_\_\_  
 FRIABLE: (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: 3 tiles

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>
DESCRIPTION	<u>3 tiles</u>	

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
 COMMENTS 3 tiles

INSPECTOR: Charles Spear ACCREDITATION NO. IAA-21-24354  
 SIGNATURE: Charles Spear DATE: 4/26/21 - mm



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Hls FLOOR MAIN  
 FUNCTIONAL AREA each class HOMOGENEOUS MATERIAL MOULDING MASSIVE  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER X  
 DESCRIPTION OF MATERIAL MOULDING MASSIVE

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 11 Cpr

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC X FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

MOULDING MASSIVE  
 APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) \_\_\_\_\_ (LF) 11 Cpr  
 FRIABLE: \_\_\_\_\_ (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) 1

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: \_\_\_\_\_

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE _____	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>

DESCRIPTION OFH

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
 COMMENTS OFH

INSPECTOR: Charles Spear ACCREDITATION NO. EPD-21-2435A  
 SIGNATURE: Charles Spear DATE: 4/26/21 - MW



# RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/3 FLOOR MAN  
FUNCTIONAL AREA Lab 6 HOMOGENEOUS MATERIAL ebonite top  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING CEILING WALLS OTHER x  
DESCRIPTION OF MATERIAL ebonite

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC x FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION ebonite conk. top

APPROXIMATE AMOUNT OF MATERIAL 200 (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) x (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x

WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) 2

CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) \_\_\_\_\_

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: OKU

POTENTIAL FOR DISTURBANCE: ACCESSIBLE x INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x

INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x

POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x

OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW y

DESCRIPTION OKU

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_

COMMENTS OKU

INSPECTOR: Charles Spear ACCREDITATION NO. 420-21-24397

SIGNATURE: Charles Spear DATE: 7/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR W/H  
 FUNCTIONAL AREA Class 6 HOMOGENEOUS MATERIAL 9" acc ceiling tiles  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 116 sq (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

DESCRIPTION

9" ceiling tiles  
 APPROXIMATE AMOUNT OF MATERIAL (SF) 116 sq (LF) \_\_\_\_\_  
 FRIABLE: (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: off

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE _____	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>

DESCRIPTION off

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
 COMMENTS off

INSPECTOR: Charles Spear ACCREDITATION NO. ERO-21-24390  
 SIGNATURE: Charles Spear DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR M/W  
 FUNCTIONAL AREA ab-7 HOMOGENEOUS MATERIAL 9" fen w  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" fen w

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 km (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR x CEILING \_\_\_\_\_

DESCRIPTION

9" fen w  
 APPROXIMATE AMOUNT OF MATERIAL (SF) 1 km (LF) \_\_\_\_\_  
 FRIABLE: \_\_\_\_\_ (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: 1 mtr

POTENTIAL FOR DISTURBANCE: ACCESSIBLE x INACCESSIBLE \_\_\_\_\_  
 POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE x LOW \_\_\_\_\_  
 POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 DESCRIPTION Ofu

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
 COMMENTS Ofu

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-2489A  
 SIGNATURE: Charles Spear DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAIN  
 FUNCTIONAL AREA Class 6 HOMOGENEOUS MATERIAL 9" olive vat  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" olive vat

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 Ke m (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR x CEILING \_\_\_\_\_

DESCRIPTION 9" olive vat

APPROXIMATE AMOUNT OF MATERIAL (SF) 1 Ke m (LF) \_\_\_\_\_

FRIABLE: (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) x

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: intact

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>x</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH	MODERATE LOW <u>x</u>
INFLUENCE OF VIBRATION:	HIGH	MODERATE LOW <u>x</u>
POTENTIAL FOR AIR EROSION:	HIGH	MODERATE LOW <u>x</u>
OVERALL RATING:	HIGH	MODERATE LOW <u>x</u>
DESCRIPTION	<u>off</u>	

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
 COMMENTS off

INSPECTOR: Charles Spear ACCREDITATION NO. IRD - 21-24394  
 SIGNATURE: Charles Spear DATE: 4/20/21 - m

**RECORDING FORM FOR ASBESTOS ASSESSMENT DATA**

BUILDING H/3 FLOOR MAN  
 FUNCTIONAL AREA Boys RL HOMOGENEOUS MATERIAL 9" olve var  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" olve var

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF) \_\_\_\_\_

**REINSPECTION DATA :**

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR x CEILING \_\_\_\_\_

**DESCRIPTION**

9" olve var  
 APPROXIMATE AMOUNT OF MATERIAL \_\_\_\_\_ (SF) 200 (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x

**PHYSICAL CONDITION:**

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD 9 FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: Intact

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE _____	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____
OVERALL RATING:	HIGH _____	MODERATE _____
DESCRIPTION <u>open</u>	HIGH _____	MODERATE _____

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
 COMMENTS Open

INSPECTOR: Charles Spear ACCREDITATION NO. IRP - 21-24394  
 SIGNATURE: Charles Spear DATE: 12/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING Hls FLOOR MAN  
FUNCTIONAL AREA Lab #7 (CP) HOMOGENEOUS MATERIAL 9" ceiling tiles  
TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING \_\_\_\_\_ CEILING X WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" ceiling tiles - CP

APPROXIMATE AMOUNT OF MATERIAL (SF) 116 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING X

DESCRIPTION 9" ceiling tiles

APPROXIMATE AMOUNT OF MATERIAL (SF) 116 (LF) \_\_\_\_\_  
FRIABLE: (YES) X (NO) \_\_\_\_\_  
NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD \_\_\_\_\_ FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: CP

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE _____	INACCESSIBLE <u>X</u>
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____
OVERALL RATING:	HIGH _____	MODERATE _____
DESCRIPTION <u>CP</u>	HIGH _____	MODERATE _____

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
COMMENTS CP

INSPECTOR: Charles Spear ACCREDITATION NO. ERO-21-24392  
SIGNATURE: Charles Spear DATE: 4/26/21



# RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/3 FLOOR MAIN  
FUNCTIONAL AREA Class 13/14 HOMOGENEOUS MATERIAL 9" dive vat  
TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" dive vat

APPROXIMATE AMOUNT OF MATERIAL (SF) 1160 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR x CEILING \_\_\_\_\_

## DESCRIPTION

9" dive vat  
APPROXIMATE AMOUNT OF MATERIAL (SF) 1160 (LF) \_\_\_\_\_  
FRIABLE: \_\_\_\_\_ (YES) x (NO) \_\_\_\_\_  
NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: int

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>x</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>x</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>x</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>x</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>x</u>
DESCRIPTION <u>Don</u>	HIGH _____	MODERATE _____ LOW <u>x</u>

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
COMMENTS Don

INSPECTOR: Charles Spear ACCREDITATION NO. IL0-21-2439A  
SIGNATURE: Charles Spear DATE: 4/26/20

**RECORDING FORM FOR ASBESTOS ASSESSMENT DATA**

BUILDING HH FLOOR MAN  
 FUNCTIONAL AREA grv 5 rd HOMOGENEOUS MATERIAL 9" green paint  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING X CEILING WALLS OTHER 2nd st  
 DESCRIPTION OF MATERIAL 2nd st

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF)         

**REINSPECTION DATA :**

ACBM TYPE: SURFACING          TSI          MISC          FLOOR X CEILING         

**DESCRIPTION**

9" green paint

APPROXIMATE AMOUNT OF MATERIAL (SF) 200 (LF)         

FRIABLE: (YES) X (NO)           
 NON-FRIABLE (YES)          (NO) X  
 WARNING LABELS (YES)          (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES)          (NO) X

**PHYSICAL CONDITION:**

TYPE OF DAMAGE: DETERIORATION          PHYSICAL X WATER          FIRE           
 EXTENT OF DAMAGE: LOCALIZED          DISTRIBUTED X  
 PERCENT OF DAMAGE: 0%          1-10% X 10-25%          25-100%           
 OVERALL RATING: GOOD          FAIR          POOR           
 DESCRIPTION: masonry edge near g. hole (1/2 2nd st)

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH	MODERATE LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH	MODERATE LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH	MODERATE LOW <u>X</u>
OVERALL RATING:	HIGH	MODERATE LOW <u>X</u>
DESCRIPTION	<u>Open</u>	

LOCATION IN AIR PLENUM: YES X NO           
 COMMENTS CEM

INSPECTOR: Charles Spear ACCREDITATION NO. FPD-21-2439A  
 SIGNATURE: Charles Spear DATE: 7/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAN  
 FUNCTIONAL AREA CAR HOMOGENEOUS MATERIAL 9" brown VPT  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING X CEILING WALLS OTHER  
 DESCRIPTION OF MATERIAL 9" VPT

APPROXIMATE AMOUNT OF MATERIAL (SF) 544 (LF)         

REINSPECTION DATA :

ACBM TYPE: SURFACING          TSI          MISC          FLOOR X CEILING         

DESCRIPTION 9" brown part VPT

APPROXIMATE AMOUNT OF MATERIAL (SF) 644 (LF)         

FRIABLE: (YES) X (NO)           
 NON-FRIABLE (YES)          (NO) X  
 WARNING LABELS (YES)          (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES)          (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION          PHYSICAL X WATER          FIRE           
 EXTENT OF DAMAGE: LOCALIZED          DISTRIBUTED X  
 PERCENT OF DAMAGE: 0%          1-10%          10-25%          25-100%           
 OVERALL RATING: GOOD          FAIR          POOR           
 DESCRIPTION: QPL

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>        </u>	INACCESSIBLE <u>        </u>
POTENTIAL FOR CONTACT:	HIGH <u>        </u>	MODERATE <u>        </u>
INFLUENCE OF VIBRATION:	HIGH <u>        </u>	MODERATE <u>        </u>
POTENTIAL FOR AIR EROSION:	HIGH <u>        </u>	MODERATE <u>        </u>
OVERALL RATING:	HIGH <u>        </u>	MODERATE <u>        </u>
DESCRIPTION <u>QPL</u>	HIGH <u>        </u>	MODERATE <u>        </u>

LOCATION IN AIR PLENUM: YES X NO           
 COMMENTS QPL

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-2439A  
 SIGNATURE: Charles Spear DATE: 4/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR 1st  
 FUNCTIONAL AREA halls HOMOGENEOUS MATERIAL red 9" VAT  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" red VAT

APPROXIMATE AMOUNT OF MATERIAL (SF) 10V (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION 9" red VAT

APPROXIMATE AMOUNT OF MATERIAL (SF) 10V (LF) \_\_\_\_\_  
 FRIABLE: (YES) X (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) X  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: intact

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH	MODERATE
INFLUENCE OF VIBRATION:	HIGH	MODERATE <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH	MODERATE
OVERALL RATING:	HIGH	MODERATE
DESCRIPTION <u>OK</u>	HIGH	MODERATE

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
 COMMENTS OK

INSPECTOR: Charles Spaul ACCREDITATION NO. IAD-21-24392  
 SIGNATURE: Charles Spaul DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING HLS FLOOR Ward  
 FUNCTIONAL AREA class 3 HOMOGENEOUS MATERIAL 9" grey UAT  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING x CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 9" grey UAT  
 APPROXIMATE AMOUNT OF MATERIAL (SF) 1160 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR x CEILING \_\_\_\_\_

DESCRIPTION 9" grey UAT

APPROXIMATE AMOUNT OF MATERIAL (SF) 1160 (LF) \_\_\_\_\_  
 FRIABLE: (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) y

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: Intact

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>x</u>	INACCESSIBLE
POTENTIAL FOR CONTACT:	HIGH	MODERATE LOW <u>x</u>
INFLUENCE OF VIBRATION:	HIGH	MODERATE LOW <u>x</u>
POTENTIAL FOR AIR EROSION:	HIGH	MODERATE LOW <u>x</u>
OVERALL RATING:	HIGH	MODERATE LOW <u>x</u>
DESCRIPTION		

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
 COMMENTS \_\_\_\_\_

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-24354  
 SIGNATURE: Charles Spear DATE: 4/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAN  
 FUNCTIONAL AREA Room 9 HOMOGENEOUS MATERIAL 9" olive VAS  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING X CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL 1/20

APPROXIMATE AMOUNT OF MATERIAL (SF) 112 (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR X CEILING \_\_\_\_\_

DESCRIPTION 9" olive spect not

APPROXIMATE AMOUNT OF MATERIAL (SF) 112 (LF) \_\_\_\_\_  
 FRIABLE: (YES) ✓ (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) \_\_\_\_\_  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL X WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% X 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD X FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: only

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>X</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>X</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>X</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>X</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>X</u>
DESCRIPTION	<u>only</u>	

LOCATION IN AIR PLENUM: YES X NO \_\_\_\_\_  
 COMMENTS Open

INSPECTOR: Charles Spear ACCREDITATION NO. 100-21-24354  
 SIGNATURE: Charles Spear DATE: 4/26/21



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAN  
 FUNCTIONAL AREA room 9 HOMOGENEOUS MATERIAL wooding marble  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING CEILING WALLS OTHER X  
 DESCRIPTION OF MATERIAL

APPROXIMATE AMOUNT OF MATERIAL (SF) (LF) 1 K per

REINSPECTION DATA :

ACBM TYPE: SURFACING TSI MISC X FLOOR CEILING

DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) (LF) 1 K per  
 FRIABLE: (YES) X (NO)  
 NON-FRIABLE (YES) (NO) X  
 WARNING LABELS (YES) (NO) X  
 CHANGE FROM INITIAL AHERA REPORT (YES) (NO) X

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION PHYSICAL X WATER FIRE  
 EXTENT OF DAMAGE: LOCALIZED DISTRIBUTED X  
 PERCENT OF DAMAGE: 0% 1-10% X 10-25% 25-100%  
 OVERALL RATING: GOOD X FAIR POOR  
 DESCRIPTION: OFM

POTENTIAL FOR DISTURBANCE: ACCESSIBLE X INACCESSIBLE  
 POTENTIAL FOR CONTACT: HIGH MODERATE LOW X  
 INFLUENCE OF VIBRATION: HIGH MODERATE LOW X  
 POTENTIAL FOR AIR EROSION: HIGH MODERATE LOW X  
 OVERALL RATING: HIGH MODERATE LOW X  
 DESCRIPTION OFM

LOCATION IN AIR PLENUM: YES X NO  
 COMMENTS OFM

INSPECTOR: Charles Suer ACCREDITATION NO. INO-21-24392  
 SIGNATURE: Charles Suer DATE: 4/26/21

## RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR MAN  
FUNCTIONAL AREA walls HOMOGENEOUS MATERIAL ceiling fibres / mastic  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING CEILING ☒ WALLS OTHER  
DESCRIPTION OF MATERIAL 1 bag 2 ceiling fibres / m

APPROXIMATE AMOUNT OF MATERIAL (SF) 10K+ (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING ☒

## DESCRIPTION

APPROXIMATE AMOUNT OF MATERIAL (SF) 10K (LF) \_\_\_\_\_

FRIABLE: \_\_\_\_\_ (YES) ☒ (NO) \_\_\_\_\_

NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ☒

WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ☒

CHANGE FROM INITIAL AHERA REPORT \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) ☒

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL ☒ WATER \_\_\_\_\_ FIRE \_\_\_\_\_

EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED ☒

PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% ☒ 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_

OVERALL RATING: GOOD ☒ FAIR \_\_\_\_\_ POOR \_\_\_\_\_

DESCRIPTION: infect

POTENTIAL FOR DISTURBANCE: ACCESSIBLE ☒ INACCESSIBLE \_\_\_\_\_

POTENTIAL FOR CONTACT: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ☒

INFLUENCE OF VIBRATION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ☒

POTENTIAL FOR AIR EROSION: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ☒

OVERALL RATING: \_\_\_\_\_ HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW ☒

DESCRIPTION Op4

LOCATION IN AIR PLENUM: YES ☒ NO \_\_\_\_\_

COMMENTS OP4

INSPECTOR: Charles Spaw ACCREDITATION NO. IRO-21-2439A

SIGNATURE: Charles Spaw DATE: 4/26/21



## RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING HHS FLOOR MAN  
FUNCTIONAL AREA Halls HOMOGENEOUS MATERIAL wooding waste  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING CEILING WALLS OTHER ☒  
DESCRIPTION OF MATERIAL woody waste

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 1024

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC ☒ FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

## DESCRIPTION

MOVED in matrices  
APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 1024  
FRIABLE: (YES) ☒ (NO) \_\_\_\_\_  
NON-FRIABLE (YES) \_\_\_\_\_ (NO) ☒  
WARNING LABELS (YES) \_\_\_\_\_ (NO) ☒  
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) ☒

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL ☒ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED ☒  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% ☒ 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD ☒ FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: OK

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <input checked="" type="checkbox"/>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <input checked="" type="checkbox"/>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW _____
DESCRIPTION	<u>OK</u>	

LOCATION IN AIR PLENUM: YES ☒ NO \_\_\_\_\_  
COMMENTS OK

INSPECTOR: Charles Spew ACCREDITATION NO. IDA-21-24392  
SIGNATURE: Chris DATE: 10/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING 413 FLOOR MAN  
 FUNCTIONAL AREA halls HOMOGENEOUS MATERIAL wall texture  
 TYPE OF SUSPECT MATERIAL SURFACING x TSI \_\_\_\_\_  
 FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
 DESCRIPTION OF MATERIAL wall texture

APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) \_\_\_\_\_

REINSPECTION DATA :

ACBM TYPE: SURFACING x TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION wall texture

APPROXIMATE AMOUNT OF MATERIAL (SF) NDL (LF) \_\_\_\_\_  
 FRIABLE: (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) x

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD f FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: intal

POTENTIAL FOR DISTURBANCE: ACCESSIBLE x INACCESSIBLE \_\_\_\_\_  
 POTENTIAL FOR CONTACT: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 INFLUENCE OF VIBRATION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 POTENTIAL FOR AIR EROSION: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 OVERALL RATING: HIGH \_\_\_\_\_ MODERATE \_\_\_\_\_ LOW x  
 DESCRIPTION con

LOCATION IN AIR PLENUM: YES x NO \_\_\_\_\_  
 COMMENTS con

INSPECTOR: Charles Spear ACCREDITATION NO. IR0-21-24392  
 SIGNATURE: Charles Spear DATE: 4/20/21



# RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H13 FLOOR Mt 2  
FUNCTIONAL AREA Class 2 HOMOGENEOUS MATERIAL 9" grey VMT  
TYPE OF SUSPECT MATERIAL SURFACING TSI  
FLOORING ☒ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER \_\_\_\_\_  
DESCRIPTION OF MATERIAL 9" grey VMT

APPROXIMATE AMOUNT OF MATERIAL (SF) 1800 (LF) \_\_\_\_\_

## REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC \_\_\_\_\_ FLOOR ☒ CEILING \_\_\_\_\_

DESCRIPTION 9" grey tile

APPROXIMATE AMOUNT OF MATERIAL (SF) 1800 (LF) \_\_\_\_\_  
FRIABLE: (YES) ☒ (NO) \_\_\_\_\_  
NON-FRIABLE (YES) \_\_\_\_\_ (NO) ☒  
WARNING LABELS (YES) \_\_\_\_\_ (NO) ☒  
CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) ☒

## PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL ☒ WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED ☒  
PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% ☒ 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
OVERALL RATING: GOOD ☒ FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
DESCRIPTION: intact

	ACCESSIBLE	INACCESSIBLE
POTENTIAL FOR DISTURBANCE:	HIGH	MODERATE
POTENTIAL FOR CONTACT:	HIGH	MODERATE
INFLUENCE OF VIBRATION:	HIGH	MODERATE
POTENTIAL FOR AIR EROSION:	HIGH	MODERATE
OVERALL RATING:	HIGH	MODERATE
DESCRIPTION	<u>0.01</u>	

LOCATION IN AIR PLENUM: YES ☒ NO \_\_\_\_\_  
COMMENTS 0.01

INSPECTOR: Charles Spear ACCREDITATION NO. IP0-21-24351A  
SIGNATURE: Charles Spear DATE: 4/26/21

RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING 4/4 FLOOR man  
 FUNCTIONAL AREA class 1 HOMOGENEOUS MATERIAL 1 by 2 / wastes  
 TYPE OF SUSPECT MATERIAL SURFACING TSI  
 FLOORING CEILING x WALLS OTHER  
 DESCRIPTION OF MATERIAL 1 by 2 files + mortar

APPROXIMATE AMOUNT OF MATERIAL (SF) 14 m (LF)         

REINSPECTION DATA :

ACBM TYPE: SURFACING          TSI          MISC          FLOOR          CEILING x

DESCRIPTION 1 by 2 files / mortar

APPROXIMATE AMOUNT OF MATERIAL (SF) 14 m (LF)         

FRIABLE: (YES) x (NO)           
 NON-FRIABLE (YES)          (NO) y  
 WARNING LABELS (YES)          (NO) x  
 CHANGE FROM INITIAL AHERA REPORT (YES)          (NO) x

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION          PHYSICAL y WATER          FIRE           
 EXTENT OF DAMAGE: LOCALIZED          DISTRIBUTED x  
 PERCENT OF DAMAGE: 0%          1-10% x 10-25%          25-100%           
 OVERALL RATING: GOOD x FAIR          POOR           
 DESCRIPTION: 14 feet

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>x</u>	INACCESSIBLE <u>        </u>
POTENTIAL FOR CONTACT:	HIGH <u>        </u>	MODERATE <u>        </u>
INFLUENCE OF VIBRATION:	HIGH <u>        </u>	MODERATE <u>        </u>
POTENTIAL FOR AIR EROSION:	HIGH <u>        </u>	MODERATE <u>        </u>
OVERALL RATING:	HIGH <u>        </u>	MODERATE <u>        </u>
DESCRIPTION <u>One</u>	HIGH <u>        </u>	MODERATE <u>        </u>

LOCATION IN AIR PLENUM: YES x NO           
 COMMENTS one

INSPECTOR: Charles Spivey ACCREDITATION NO. EPD-21-24390  
 SIGNATURE: Chab S DATE: 4/26/21 - man



RECORDING FORM FOR ASBESTOS ASSESSMENT DATA

BUILDING H/S FLOOR 1st  
 FUNCTIONAL AREA Class HOMOGENEOUS MATERIAL \_\_\_\_\_  
 TYPE OF SUSPECT MATERIAL SURFACING \_\_\_\_\_ TSI \_\_\_\_\_  
 FLOORING \_\_\_\_\_ CEILING \_\_\_\_\_ WALLS \_\_\_\_\_ OTHER x  
 DESCRIPTION OF MATERIAL MODERN waste

APPROXIMATE AMOUNT OF MATERIAL (SF) 1K (LF) 1K

REINSPECTION DATA :

ACBM TYPE: SURFACING \_\_\_\_\_ TSI \_\_\_\_\_ MISC x FLOOR \_\_\_\_\_ CEILING \_\_\_\_\_

DESCRIPTION

MODERN waste  
 APPROXIMATE AMOUNT OF MATERIAL (SF) \_\_\_\_\_ (LF) 1K  
 FRIABLE: \_\_\_\_\_ (YES) x (NO) \_\_\_\_\_  
 NON-FRIABLE \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 WARNING LABELS \_\_\_\_\_ (YES) \_\_\_\_\_ (NO) x  
 CHANGE FROM INITIAL AHERA REPORT (YES) \_\_\_\_\_ (NO) y

PHYSICAL CONDITION:

TYPE OF DAMAGE: DETERIORATION \_\_\_\_\_ PHYSICAL x WATER \_\_\_\_\_ FIRE \_\_\_\_\_  
 EXTENT OF DAMAGE: LOCALIZED \_\_\_\_\_ DISTRIBUTED x  
 PERCENT OF DAMAGE: 0% \_\_\_\_\_ 1-10% x 10-25% \_\_\_\_\_ 25-100% \_\_\_\_\_  
 OVERALL RATING: GOOD x FAIR \_\_\_\_\_ POOR \_\_\_\_\_  
 DESCRIPTION: infad

POTENTIAL FOR DISTURBANCE:	ACCESSIBLE <u>x</u>	INACCESSIBLE _____
POTENTIAL FOR CONTACT:	HIGH _____	MODERATE _____ LOW <u>x</u>
INFLUENCE OF VIBRATION:	HIGH _____	MODERATE _____ LOW <u>x</u>
POTENTIAL FOR AIR EROSION:	HIGH _____	MODERATE _____ LOW <u>x</u>
OVERALL RATING:	HIGH _____	MODERATE _____ LOW <u>x</u>
DESCRIPTION	<u>0</u>	

LOCATION IN AIR PLENUM: YES \_\_\_\_\_ NO \_\_\_\_\_  
 COMMENTS 0

INSPECTOR: Charles Spaw ACCREDITATION NO. ISO-21-24392  
 SIGNATURE: Charles Spaw DATE: 4/26/21 - Wm

**APPENDIX 3.0**  
**REGULATIONS**



An official website of the United States government.



## Asbestos Laws and Regulations

This page provides a listing of the laws and regulations pertaining to asbestos implemented by EPA and certain other federal agencies. Learn more about EPA actions to protect the public from asbestos exposure including banned/prohibited uses. [link to page at beginning of this file]

### EPA Asbestos-Related Laws

- [The Asbestos Hazard Emergency Response Act \(AHERA\)](#)
- [The Asbestos Information Act \(AIA\)](#)
- [The Asbestos School Hazard Abatement Reauthorization Act \(ASHARA\)](#)
- [The Clean Air Act \(CAA\)](#)
- [Safe Drinking Water Act \(SDWA\)](#)
- [The Comprehensive Environmental Response, Compensation and Liability Act \(CERCLA\)](#)

### EPA Asbestos Regulations

- [Restrictions on Discontinued Uses of Asbestos \(40 CFR Parts 9 and 721\)](#)
- [Asbestos-Containing Materials in Schools Rule \(40 CFR Part 763, Subpart E\)](#)
- [Asbestos Worker Protection Rule \(40 CFR Part 763, Subpart G\)](#)
- [Asbestos Ban and Phaseout Rule \(Remanded\) \(40 CFR Part 763, Subpart I\)](#)
- [Asbestos National Emission Standard for Hazardous Air Pollutants \(NESHAP\) Regulations \(40 CFR Part 61, Subpart M\)](#)
- [CERCLA Hazardous Substances and Reportable Quantities](#)

### Other Federal Agencies with Asbestos Regulations

- [Occupational Safety and Health Administration \(OSHA\)](#)
- [Consumer Product Safety Commission \(CPSC\)](#)
- [Mine Safety and Health Administration \(MSHA\)](#)

## EPA Asbestos-Related Laws

### **The Asbestos Hazard Emergency Response Act (AHERA) (Toxic Substances Control Act (TSCA) Title II)**

This law required EPA to promulgate regulations (e.g., the Asbestos-Containing Materials in Schools Rule) requiring local educational agencies to inspect their school buildings for asbestos-containing building material, prepare asbestos management plans and perform asbestos response actions to prevent or reduce asbestos hazards. AHERA also tasked EPA with developing a model plan for states for accrediting persons conducting asbestos inspection and corrective-action

activities at schools. The Toxic Substances Control Act defines asbestos as the asbestiform varieties of: chrysotile (serpentine); crocidolite (riebeckite); amosite (cummingtonite/grunerite); anthophyllite; tremolite; and actinolite.

- [TSCA Subchapter II: Asbestos Hazard Emergency Response \(15 U.S.C. § 2641-2656\)](#)

### **Asbestos Information Act (Public Law 100-577)**

This law helped to provide transparency and identify the companies making certain types of asbestos-containing products by requiring manufacturers to report production to the EPA.

- [15 U.S.C. § 2607\(f\)](#)

### **Asbestos School Hazard Abatement Reauthorization Act (ASHARA)**

This law extended funding for the asbestos abatement loan and grant program for schools. ASHARA also directed EPA to increase the number of training hours required for the training disciplines under the Asbestos Model Accreditation Plan (MAP) and to expand the accreditation requirements to cover asbestos abatement projects in all public and commercial buildings in addition to schools.

Docket ID: OPTS-62048E; FRL-3269-8

- [Asbestos School Hazard Abatement Reauthorization Act of 1990](#)
- [Asbestos Model Accreditation Plan](#)
- [February 3, 1994 Federal Register Notice: Asbestos Model Accreditation Plan](#)

### **Clean Air Act (CAA) (42 USC § 7401 et seq.)**

This law defines the EPA's responsibilities for protecting and improving the nation's air quality and the stratospheric ozone layer and includes provisions for the EPA to set national emission standards for hazardous air pollutants, including asbestos.

- [Section 112- National Emission Standards for Hazardous Air Pollutants](#)

### **Safe Drinking Water Act (SDWA)**

The Safe Drinking Water Act (SDWA) is the federal law that helps ensure the quality of Americans' drinking water. Under the SDWA, EPA sets standards for drinking water quality and oversees the states, localities, and water suppliers who implement those standards.

### **Comprehensive Environmental Response, Compensation and Liability Act (CERCLA)**

This law, also known as Superfund, was enacted to address abandoned hazardous waste sites in the U.S. The law has subsequently been amended, by the Superfund Amendments and Reauthorization Act of 1986 (SARA), and the Small Business Liability Relief and Brownfields Revitalization Act of 2002. CERCLA authority may be appropriate to respond to the release or potential release of asbestos into the environment.

## **EPA Asbestos Regulations**



**Restrictions on Discontinued Uses of Asbestos Rule**

This final rule strengthens the Agency's ability to rigorously review an expansive list of asbestos products that are no longer on the market before they could be sold again in the United States. Persons subject to the rule are required to notify EPA at least 90 days before commencing any manufacturing, importing, or processing of asbestos or asbestos-containing products covered under the rule. These uses are prohibited until EPA conducts a thorough review of the notice and puts in place any necessary restrictions or prohibits use.

Docket ID: EPA-HQ-OPPT-2018-0159; FRL 9991-33

- [40 CFR Parts 9 and 721 – Restrictions on Discontinued Uses of Asbestos](#)

**Asbestos-Containing Materials in Schools Rule**

Pursuant to the Asbestos Hazard Emergency Response Act (AHERA), the Asbestos-Containing Materials in Schools rule requires local education agencies to inspect their school buildings for asbestos-containing building material, prepare asbestos management plans and perform asbestos response actions to prevent or reduce asbestos hazards. Public school districts and non-profit private schools, including charter schools and schools affiliated with religious institutions (collectively called local education agencies) are subject to the rule's requirements.

Docket ID: OPTS-62048E; FRL-3269-8

- [Asbestos-Containing Materials in Schools Rule \(40 CFR Part 763, Subpart E\)](#)
  - [Interim Transmission Electron Microscopy \(TEM\) Analytical Methods \(Appendix A to Subpart E of 40 CFR Part 763\)](#)
  - [Asbestos Model Accreditation Plan \(Appendix C to Subpart E of 40 CFR Part 763\)](#)
  - [Transport and Disposal of Asbestos Waste \(Appendix D to Subpart E of 40 CFR Part 763\)](#)
  - [Interim Method of the Determination of Asbestos in Bulk Insulation Samples \(Appendix E to Subpart E of 40 CFR Part 763\)](#)

**EPA Asbestos Worker Protection Rule**

Through the authority of Section 6 of the Toxic Substances Control Act (TSCA) the EPA extended worker protection requirements to state and local government employees involved in asbestos work who were not previously covered by the the Occupational Safety and Health Administration's (OSHA) asbestos regulations.

Docket ID: OPPTS-62125B; FRL-6751-3

- [40 CFR Part 763, Subpart G – Asbestos Worker Protection](#)

**Asbestos Ban and Phaseout Rule (Remanded )**

On July 12, 1989, the EPA issued a final rule banning most asbestos-containing products. In 1991, this regulation was overturned by the Fifth Circuit Court of Appeals. However, as a result of the Court's decision, only a few asbestos-containing products remain banned.

[See Asbestos Ban and Phase-out Federal Register notices.](#)

Docket ID: OPTS-62048E; FRL-3269-8

- 40 CFR Part 763, Subpart I -- Prohibition of the Manufacture, Importation, Processing and Distribution in Commerce of Certain Asbestos-Containing Products; Labeling Requirements

### **Asbestos National Emission Standards for Hazardous Air Pollutants (NESHAP)**

The asbestos NESHAP regulations specify work practices for asbestos to be followed during demolitions and renovations of all structures, installations, and buildings (excluding residential buildings that have four or fewer dwelling units). The regulations require the owner of the building or the operator to notify the appropriate state agency before any demolition, or before any renovations of buildings that could contain a certain threshold amount of asbestos or asbestos-containing material. In addition, particular manufacturing and fabricating operations either cannot emit visible emissions into the outside air or must follow air cleaning procedures, as well as follow certain requirements when removing asbestos-containing waste.

Docket ID: OAR-2002-0082, FRL-7561-2

- 40 CFR Part 61, Subpart M (Complete Rule)
  - 40 CFR §61.145—Standard for demolition and renovation
  - 40 CFR §61.150—Standard for waste disposal for manufacturing, fabricating, demolition, renovation, and spraying operations

### **CERCLA Hazardous Substances and Reportable Quantities**

Asbestos is designated as a hazardous substance with a reportable quantity in the Superfund regulations.

- 40 CFR Part 302.4 - Designation of Hazardous Substances and Reportable Quantities

### **Other Federal Agencies with Asbestos Regulations**

#### **Occupational Safety and Health Administration (OSHA)**

OSHA oversees the working conditions for U.S. workers by implementing and managing occupational safety and health standards. The following regulations pertain to handling asbestos in the workplace.

- Asbestos General Standard—Specification of permissible exposure limits, engineering controls, worker training, labeling, respiratory protection, and disposal of asbestos waste
  - 29 CFR 1910.1001
- Asbestos Construction Standard—Covers construction work involving asbestos, including work practices during demolition and renovation, worker training, disposal of asbestos waste, and specification of permissible exposure limits
  - 29 CFR 1926.1101



**Consumer Product Safety Commission (CPSC)**

The CPSC protects consumers and families from consumer products that pose a fire, electrical, chemical, or mechanical hazard or can injure children. Below are the following CPSC bans or restrictions on asbestos-containing products:

- Emberizing Materials
  - 16 CFR Part 1305
- Patching Compounds
  - 16 CFR Part 1304
- Asbestos Containing Garments for General Use
  - 16 CFR § 1500.17(a)(7)

**Mine Safety and Health Administration (MSHA)**

MSHA is responsible for overseeing the safety and health of miners in the U.S. The following MSHA regulations apply to asbestos in mines:

- Surface Mines: exposure limits, engineering controls, and respiratory protection measures for workers in surface mines
  - 30 CFR part 56, subpart D
- Underground Mines: exposure limits, engineering controls, and respiratory protection measures for workers in underground mines
  - 30 CFR part 57, subpart D

## Final Asbestos Rule

In April 2019 EPA issued a final rule to ensure that asbestos products that are no longer on the market cannot return to commerce without the Agency evaluating them and putting in place any necessary restrictions or prohibiting use. [Learn more.](#)

LAST UPDATED ON SEPTEMBER 25, 2020

THIS IS TO CERTIFY THAT  
**CHARLES SPEAR**  
HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE  
for  
**ONLINE AHERA ASBESTOS INSPECTOR REFRESHER**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 02/23/2021

Course Location: Portland, OR

Certificate: IRO-21-2439A



4-Hour Online AHERA Inspector Refresher  
Training: AHERA is the Asbestos Hazard  
Emergency Response Act enacting Title II of  
Toxic Substance Control Act (TSCA)

Expiration Date: 02/23/2022

For verification of the authenticity of this  
certificate contact:

PBS Engineering and Environmental Inc.  
4412 S Corbett Avenue  
Portland, Oregon 97239  
503.248.1939

A handwritten signature in black ink, appearing to read 'Andy Fridley', is written over a horizontal line.

Andy Fridley, Instructor